

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent Number: 7,161,440
Issue Date: January 9, 2007
Name of Patentee: David Meltzer
Application No.: 10/733,143
Filing Date: December 11, 2003
Confirmation No.: 7388
Title of Invention: Temperature Compensation Circuit

**REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
FOR PTO MISTAKE (37 CFR §1.322(a))**

Sir:

It is noted that an error appears or errors appear in this patent of a clerical, typographical or minor nature or character, as more fully described below, due to a mistake by the U.S. Patent and Trademark Office.

Attached hereto is Form PTO-1050.

The exact page(s) and line number(s) where the error(s) occur in the patent are:

Column 20

Line 33, please change "summing output node" to --summing node--.

Column 23

Line 33, please change "said output third lead" to --said third lead--.

REQUEST FOR CERTIFICATE OF CORRECTION OF
PATENT FOR PTO MISTAKE (37 CFR §1.322(a))

Patentee's undersigned attorney may be reached at the telephone number listed below. All correspondence should continue to be directed to our address listed below.

Respectfully submitted,

/Rosalio Haro/
Rosalio Haro
Registration No. 42,633

Please address all correspondence to:
Epson Research and Development, Inc.
2580 Orchard Parkway, Suite 225
San Jose, CA 95131
Customer No. 20178
Telephone: (408) 952-6131
Facsimile: (408) 954-9058

Date: March 18, 2008

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO.: 7,161,440
APPLICATION NO.: 10/733,143
ISSUE DATE: January 9, 2007
INVENTOR(S): David Meltzer

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 20

Line 33, please change "summing output node" to --summing node--.

Column 23

Line 33, please change "said output third lead" to --said third lead--.

MAILING ADDRESS OF SENDER:
Epson Research and Development, Inc.
Intellectual Property Department
2580 Orchard Parkway, Suite 225
San Jose, CA 95131

FORM PTO 1050